PROPERTY INSPECTION REPORT DISCLOSURE

This report is being provided for information purposes only and your reliance on it is at your own risk. Auction.com and seller make no representations or warranties of any kind with respect to the services provided by the third party company(s) who prepared this report including, but not limited to, the accuracy, completeness, timeliness, merchantability or fitness for a particular purpose. You understand that Auction.com and seller have no obligation or duty to inform you or correct information in the report, even if Auction.com or seller learn that the report contains incorrect information; nor will Auction.com or seller have any obligation to inform you or update the report if they learn new information not reflected in the report. You further understand that neither Auction.com nor Seller shall be liable to you for any loss or injury arising out of or caused, in whole or in part, by negligent acts or omissions in procuring, compiling, collecting, interpreting, reporting, communicating or delivering the services or the report. This report does not constitute an appraisal or inspection conducted by a licensed professional.

09/06/2023

No Garage

Hot Water Not Available

Maybe Habitable: No

No

No

No

No

21

Inspection Details

Insp Type: Foreclosure

Requested: 08/26/2023

09/06/2023

[NI]

Occupancy: Vacant 0

Occ Units: Verification: Debris Present, Visual, and Yard Not Maintained see above

Uploaded:

Photo Amt:

Secure: Secured

Reason for Poor Ext Condition: severe neglect

Construction: Frame

LockBox:

Broker: Walk Thru: Yes

Tarped Roof: No AC/HVAC: No

Damaged Foundation: No

Card Left At Property: False

Pers Prop:

Ordered:

Cancelled:

Insp Price:

Prop Type:

Neighborhood:

Keys Fit:

Phone: Poor Int Condition:

Sump Pump: No Window AC:

Damaged Beyond Repair: No

Results Confirmed: YES Yes

08/26/2023

Single

Stable

Interior

Furnace

Hazard:

Reg By:

Inspected:

Int Photos:

Lawn Type:

Condition:

Hazards:

For Sale:

Sign In Yard:

Usar Symbol

Total:

Color:

Damaged Affects Safety: None

rotting trash filth

Not Available

aspenwebhook

Billed:

Value:

Grass Height 3-4 ir Roof Type: Asphalt Shingle

Garage:

Seller:

Tank:

Ext Photos

09/05/2023

Beige/Tan

[NI]

Poor

Interior

No

No

No

4

Vacancy Posting Left At Property: False Letter Delivered to Property:

Observed On Site

Personal Property

Maintenance Needed Yes

Cut Grass: Boarding: Nο Remove Snow: No

Walls: None

Utilities

Electric On: No Water On: No

Gas On: No

Height:

Bees / Wasps: No

Depth: 2 inches or less

4-6 inches

Debris: Tarp Roof:

Verified By: Other

Verified By: Other

Winterize:

Both No

No

Other Infestation: No

Interior Standing Water: No

vacant

Pool Type:

Locks:

Windows:

Walkway

Water Shut off Location:

Unknown

Verified By: Other Shared:No Gas Provider:

Vacant Data:

Electric Provider:

Full Bath:

Pool: No

Spa: No

Lawn Being Maintained: Yes

Hot Tub: No

Fountain: No

Water Feature: No

vacant

Half Bath: 0

Bedrooms: 0

Security Method: Not Secured Security Method: Not Secured Security Method: Not Secured

Water Provider:

Security Method: Not Secured Security Method: Not Secured

HOA Mainted: No

vacant

Pool Secure: Unknown Pool Drained: No More than 2" of Water: No

> More than 2" of Water: No More than 2" of Water: No

More than 2" of Water: No

Violations Present: No.

Inspection Detail Report

Property Info

309 RIDGE AVENUE HAGERSTOWN, MD 21740

everything filth decaying trash Windows Boarded: 0 Locks Changed: Yes int. Debris:

Ext. Debris: trash junk misc Doors Boarded: 0

Previously Winterized: Yes Prev. wint by: mcs Hazard Location:

Dehumidifier: Not Prese Dehumidifier Self-draining: No Water Heater: Not Present Water Heater Straped: No

Not Present Well Equipment: Personal Property Description: everything decaying trash

Property Unsecured Upon Arrival: No Property Connected to Sewer/Septic: Yes

Flooring Cond. Issue:Yes Deck Hand Rails Present:No Poor Int. Condition:No Broom Swept:No

Neighbor Confirms Vacant: Unknow Missing Electric Meter:Unknown Missing Window Covrings: Unkn Missing Interior Furniture: Unkno

Unsecured Areas

Appliances/Fixtures that are missing/damaged

Dishwasher, Dryer, Garbage Disposal, Kitchen Vent, Built-in Microwave, Oven Range, Refrigerator, Stove, Washer, Smoke

Detector, CO2 Detector, HVAC components, Toilets, Tubs/Showers, Plumbing/Fixtures, Breaker Panel

Vacant Property Factors (Exterior) , Building Exterior Surfaces Intact: Yes

Vacant Property Factors (Interior)

Vacant Property Factors (Landscape)

Lawn needs edging, Overgrown Weeds/invasive plants, Shrubs Need Trimmed, Weeds Overgrown

Vacant Property Factors (Outbuildings)

Vacant Property Factors (Pool/Hot Tub)

Escalation

Are any of the following visual from the property?

Airport: No Commercial Buildings: No Other Non-Residential Facilities: No Highway: No

Industrial Plants: No Railroad Tracks: Yes Vacant (Boarded) Homes: No Portential Haz Material: No

No Drug Activity:

Other:

Exterior Condition Data

Conforms to neighborhood: Yes Commercial Activity: No Parking - Driveway: No Zoning affects marketability: No Damage affects safety: No Parking - Street: Yes Adverse easements: No Visible signs of constr. or remodeling: No Parking - Other: No

No damages for this inspection.

Vacancy CheckList I	Details				
ICC:	Dotailo	V	acancy Date:		
		•	additoy bate.		
Reason Not ICC:					
Locks/Damage/Winterization					
Locks Changed:	Keycode ⁻		KeyCode 2: 0		
Lockbox Code:	Winterized	:	Wint Damage: No		
Damage: No					
Are These Items Still in the House?					
	No Heater:		ishwasher: No		
Stove: N	No A/C:	Yes B	reaker Box: No		
Boarding/Neighborhood					
Boarded: No	High Vandal: N	lo All Doors/Windows/Locks In Place	e/Operable: Yes		
Reason: NOTPI	ROVIDED				
Yard/Debris					
Grass Cut: Y	Yes Grass Length:	4-6 inches V	iolations: No		
Int Debris: Y	res Ext Debris:	Yes In	t Swept: No		
Raw Garbage: Y	Yes Hazardous Was	. No			
Explain:					

No violations for this inspection.

No comments for this inspection.

Comments

Electric Company: vacant . Gas Company: vacant . Water Company: vacant . Occupancy Verified by Yard Not maintained,
Debris Present, and Visual. Aspen Grove ID:
- Property is vacant and secured, debris need to be removed, yard needs maintenance ,severe neglect did not enter last doorway due to smell and trash Occupancy Verification by Visual, Debris Present, and Yard Not Maintained.

No notes for this inspection.

Not any No Access info for this inspection.

Inspection Detail Report

Property Info

309 RIDGE AVENUE HAGERSTOWN, MD 21740

Postings and Notices		
<u>PostingType</u>	<u>PostingDate</u>	
Winterization Sticker	11/01/2021	
Post Secure	11/01/2021	

Inspection Images

Vacancy Certification



Damage Photo



Lockbox on Door Visible



Damage Photo

Lockbox Access Code Us



Damage Photo

Front View Front View Front View





Side View



Side View

Kitchen



Exterior Photo

Exterior Photo

Address Number View



Rear View

Street Sign

Street Sign



Front View Front View Front View

Key Inside Lockbox (upor



Damage Photo Damage Photo Exterior Photo







Neighborhood



Neighborhood

Common Areas

Street Sign Bedroom Bathroom